




The chapel interior before renovation

**Reeth Evangelical
Congregational Church
Photographs before and after Phase 4
building work 2020**




South wall of chapel after renovation





The north gable



The south gable



North window masonry



The repaired roof